

Перв. примен.

ВИНИ.467459.001

Справа. №

Подп. и дата

Инв. № дубл.

Взам. инв. №

Подп. и дата

Инв. № подл.

ВИНИ.467459.001 ЭЗ

XS1

Цепь	↔
GND	A1
GND	A12
VBUS	A4
VBUS	A9
CC1	A5
CC2	B5
D+	A6
D+	B6
D-	A7
D-	B7
SBU1	A8
SBU2	B8
SH	SH
BL	BL

XS2

Цепь	↔
5V	1
GND	2

XP1

Цепь	→
VTref	1
NC	2
nTRST	3
GND	4
TDI	5
GND	6
TMS	7
GND	8
TCK	9
GND	10
RTCK	11
GND	12
TDO	13
GND	14
RESET	15
GND	16
DBGREQ	17
GND	18
5V	19
GND	20

XS3

Цепь	↔
5V	1
GND	2

XS4

Цепь	↔
5V	1
GND	2

XS5

Цепь	↔
5V	1
GND	2

XS6

Цепь	↔
5V	1
GND	2

XS7

Цепь	↔
5V	1
GND	2

XS8

Цепь	↔
5V	1
GND	2

XS9

Цепь	↔
5V	1
GND	2

XS10

Цепь	↔
5V	1
GND	2

XS11

Цепь	↔
5V	1
GND	2

XS12

Цепь	↔
5V	1
GND	2

XS13

Цепь	↔
5V	1
GND	2

XS14

Цепь	↔
5V	1
GND	2

XS15

Цепь	↔
5V	1
GND	2

XS16

Цепь	↔
5V	1
GND	2

XS17

Цепь	↔
5V	1
GND	2

XS18

Цепь	↔
5V	1
GND	2

XS19

Цепь	↔
5V	1
GND	2

XS20

Цепь	↔
5V	1
GND	2

XS21

Цепь	↔
5V	1
GND	2

XS22

Цепь	↔
5V	1
GND	2

XS23

Цепь	↔
5V	1
GND	2

XS24

Цепь	↔
5V	1
GND	2

XS25

Цепь	↔
5V	1
GND	2

XS26

Цепь	↔
5V	1
GND	2

XS27

Цепь	↔
5V	1
GND	2

XS28

Цепь	↔
5V	1
GND	2

XS29

Цепь	↔
5V	1
GND	2

XS30

Цепь	↔
5V	1
GND	2

XS31

Цепь	↔
5V	1
GND	2

XS32

Цепь	↔
5V	1
GND	2

XS33

Цепь	↔
5V	1
GND	2

XS34

Цепь	↔
5V	1
GND	2

XS35

Цепь	↔
5V	1
GND	2

XS36

Цепь	↔
5V	1
GND	2

XS37

Цепь	↔
5V	1
GND	2

XS38

Цепь	↔
5V	1
GND	2

XS39

Цепь	↔
5V	1
GND	2

XS40

Цепь	↔
5V	1
GND	2

XS41

Цепь	↔
5V	1
GND	2

XS42

Цепь	↔
5V	1
GND	2

XS43

Цепь	↔
5V	1
GND	2

XS44

Цепь	↔
5V	1
GND	2

XS45

Цепь	↔
5V	1
GND	2

XS46

Цепь	↔
5V	1
GND	2

XS47

Цепь	↔
5V	1
GND	2

XS48

Цепь	↔
5V	1
GND	2

XS49

Цепь	↔
5V	1
GND	2

XS50

Цепь	↔
5V	1
GND	2

XS51

Цепь	↔
5V	1
GND	2

XS52

Цепь	↔
5V	1
GND	2

XS53

Цепь	↔
5V	1
GND	2

XS54

Цепь	↔
5V	1
GND	2

XS55

Цепь	↔
5V	1
GND	2

XS56

Цепь	↔
5V	1
GND	2

XS57

Цепь	↔
5V	1
GND	2

XS58

Цепь	↔
5V	1
GND	2

XS59

Цепь	↔
5V	1
GND	2

XS60

Цепь	↔
5V	1
GND	2

XS61

Цепь	↔
5V	1
GND	2

XS62

Цепь	↔
5V	1
GND	2

XS63

Цепь	↔
5V	1
GND	2

XS64

Цепь	↔
5V	1
GND	2

XS65

Цепь	↔
5V	1
GND	2

XS66

Цепь	↔
5V	1
GND	2

XS67

Цепь	↔
5V	1
GND	2

XS68

Цепь	↔
5V	1
GND	2

XS69

Цепь	↔
5V	1
GND	2

XS70

Цепь	↔
5V	1
GND	2

XS71

Цепь	↔
5V	1
GND	2

XS72

Цепь	↔
5V	1
GND	2

XS73

Цепь	↔
5V	1
GND	2

XS74

Цепь	↔
5V	1
GND	2

XS75

Цепь	↔
5V	1
GND	2

XS76

Цепь	↔
5V	1
GND	2

XS77

Цепь	↔
5V	1
GND	2

XS78

Цепь	↔
5V	1
GND	2

XS79

Цепь	↔
5V	1
GND	2

XS80

Цепь	↔
5V	1
GND	2

XS81

Цепь	↔
5V	1
GND	2

XS82

Цепь	↔
5V	1
GND	2

XS83

Цепь	↔
5V	1
GND	2

XS84

Цепь	↔
5V	1
GND	2

XS85

Цепь	↔
5V	1
GND	2

XS86

Цепь	↔
5V	1
GND	2

XS87

Цепь	↔
5V	1
GND	2

XS88

Цепь	↔
5V	1
GND	2

XS89

Цепь	↔
5V	1
GND	2

XS90

Цепь	↔
5V	1
GND	2

XS91

Цепь	↔
5V	1
GND	2

XS92

Цепь	↔
5V	1
GND	2

XS93

Цепь	↔
5V	1
GND	2

XS94

Цепь	↔
5V	1
GND	2

XS95

Цепь	↔
5V	1
GND	2

XS96

Цепь	↔
5V	1
GND	2

XS97

Цепь	↔
5V	1
GND	2

XS98

Цепь	↔
5V	1
GND	2

XS99

Цепь	↔
5V	1
GND	2

XS100

Цепь	↔
5V	1
GND	2

XS101

Цепь	↔
5V	1
GND	2

XS102

Цепь	↔
5V	1
GND	2

XS103

Цепь	↔
5V	1
GND	2

XS104

Цепь	↔
5V	1
GND	2

XS105

Цепь	↔
5V	1
GND	2

XS106

Цепь	↔
5V	1
GND	2

XS107

Цепь	↔
5V	1
GND	2

XS108

Цепь	↔
5V	1
GND	2

XS109

Цепь	↔
5V	1
GND	2

XS110

Цепь	↔
5V	1
GND	2

XS111

Цепь	↔
5V	1
GND	2

XS112

Цепь	↔
5V	1
GND	2

XS113

Цепь	↔
5V	1
GND	2

XS114

Цепь	↔
5V	1
GND	2

XS115

Цепь	↔
5V	1
GND	2

XS116

Цепь	↔
5V	1
GND	2

XS117

Цепь	↔
5V	1
GND	2

XS118

Цепь	↔
5V	1
GND	2

XS119

Цепь	↔
5V	1
GND	2

XS120

Цепь	↔
5V	1
GND	2

XS121

Цепь	↔
5V	1
GND	2

XS122

Цепь	↔
5V	1
GND	2

XS123

Цепь	↔
5V	1
GND	2

XS124

Цепь	↔
5V	1
GND	2

XS125

Цепь	↔
5V	1
GND	2

XS126

Цепь	↔
5V	1
GND	2

XS127

Цепь	↔
5V	1
GND	2

XS128

Цепь	↔
5V	1
GND	2

XS129

Цепь	↔
5V	1
GND	2

XS130

Цепь	↔
5V	1
GND	2

XS131

Цепь	↔
5V	1
GND	2

XS132

Цепь	↔
5V	1
GND	2

XS133

Цепь	↔
5V	1
GND	2

XS134

Цепь	↔
5V	1
GND	2

XS135

Цепь	↔
5V	1
GND	2

XS136

Цепь	↔
5V	1
GND	2

XS137

Цепь	↔
5V	1
GND	2

XS138

Цепь	↔
5V	1
GND	2

XS139

Цепь	↔
5V	1
GND	2

XS140

Цепь	↔
5V	1
GND	2

XS141

Цепь	↔
5V	1
GND	2

XS142

Цепь	↔
5V	1
GND	2

XS143

Цепь	↔
5V	1
GND	2

XS144

Цепь	↔
5V	1
GND	2

XS145

Цепь	↔
5V	1
GND	2

XS146

Цепь	↔
5V	1
GND	2

XS147

Цепь	↔
5V	1
GND	2

XS148

Цепь	↔
5V	1
GND	2

XS149

Цепь	↔
5V	1
GND	2

XS150

Цепь	↔
5V	1
GND	2

XS151

Цепь	↔
5V	1
GND	2

XS152

Цепь	↔
5V	1
GND	2

XS153

Цепь	↔
5V	1
GND	2

XS154

Цепь	↔
5V	1
GND	2

XS155

Цепь	↔
5V	1
GND	2

XS156

Цепь	↔
5V	1
GND	2

XS157

Цепь	↔
5V	1
GND	2

XS158

Цепь	↔
5V	1
GND	2

XS159

Цепь	↔
5V	1
GND	2

XS160

Цепь	↔
5V	1
GND	2

XS161

Цепь	↔
5V	1
GND	2

XS162

Цепь	↔
5V	1
GND	2

XS163

Цепь	↔
5V	1
GND	2

XS164

Цепь	↔
5V	1
GND	2

XS165

Цепь	↔
5V	1
GND	2

XS166

Цепь	↔
5V	1
GND	2

XS167

Цепь	↔
5V	1
GND	2

XS168

Цепь	↔
5V	